THE FOLLOWING PARTS SHOULD BE HARD SOLDERED TOGETHER: 1.01.1, 1-01.5, 1-01.3

SCALE 1:1.5

SCALE 1:1.5

SCALE 1:1.5

0.5mm PLATE SCALE 1:1.5

1mm PLATE SCALE 1:1.5

SOLDER ONTO 1-05.1

0.5mm THICK SCALE 1:1.5

SCALE 1:1.5

0.5mm THICK SS GAUGE SCALE 1:1.5

SECTION A-A SCALE 1 : 1.5

0.5mm PLATE SCALE 1:1.5

1mm PLATE SCALE 1:1.5

1mm PLATE SCALE 1:1.5

2 REQD

2 REQD

2mm THICK

2 REQD

SOLDER/BRAZE ENTIRE FIREBOX TOGETHER

RESOURCE: THE ORIGINAL DRAWINGS WERE GIVEN TO ME. THE ORIGINAL DRAWINGS WERE PUBLISHED IN A BOOK/MAGAZINE WITH THE TITLE "STEP BY STEP METALWORK 3" BY KENNETH WELLS.

TITLE

A SUPER SIMPLE TRACTION ENGINE WITH OSCILLATING STEAM ENGINE FOR BEGINNER.

DRAWING CONTENTS

PARTS AND ASSEMBLIES

JDW DRAUGHTING SERVICES
J.A.M. DE WAAL. 12 BRIGHTWELL STREET PAPAKURA 2110. NEW ZEALAND. PHONE: 0064 09 2988815. MOB: 0211791000 E-MAIL: dewaal@xtra.co.nz.

PROJECT No 08-17-00

PROJECTION

JDWDS

DATE MAY 2022

MODEL SCALE: 1:1

DWG SCALE: 1:1 @A3 OR AS SHOWN

Copyright © J.A.M. DE WAAL PAPAKURA NZ

SHEET: 02 OF 04 | A3 | No: 08-17-00-SHT-02

DRAWINGS ARE FOR PERSONAL USE ONLY NOT FOR COMMERCIAL PURPOSES