






1-2-02.1
1-2-02.2
1-2-02.5
1-2-02.4
1-2-02.7
1-2-02.3
1-2-02.6
HARD SOLDER
ENTIRE UNIT



SECTION E-E
SCALE 1 : 1.5
SECTION B-B SCALE 1 : 1.5
SECTION F-F SCALE 1 : 1.5



SECTION C-C
SCALE 1 : 1.5



SECTION I-I
SCALE 1 : 1.5



SCALE 1:1.5



HARD SOLDER
ONTO 1-2-01.1



SECTION J-J



SECTION A-A
SCALE 1 : 1.5
SECTION D-D SCALE 1 : 1.5



CAVITY
5mm DEEP



TAKE OVER ALL FROM 1-2-01.2
APPROX FLAT LENGHT=70mm



SCALE 1:1.5


SECTION K-K


2.5mm THICK
SECTION L-L


HIDDEN LINES
REMOVED FOR
CLARITY


6mm THICK
SCALE 1:2


PLUG THIS HOLE
WITH 1-2-07.3